# G25 CNC Shield

v2018.03.15

Thank you for purchasing the G25 CNC Shield. Please begin by verifying that each kit contains all the necessary parts.

□ Shield PCB

DB25 Right angle female connector

 $\Box$  1x40 male header

 $\Box$  2 shunts / jumpers

If you have any missing parts or if any parts are broken, please contact us immediately for a replacement by emailing Sales@KCLinear.com

The following instructions will guide you through the assembly process. This guide is intended to show you the steps to assemble the kit and is not meant to be a safety lesson.

Required Tools:

- Soldering Iron
- Solder
- Small wire cutters

Feel free to email us with questions. We would also love to see pictures of you completed project!

Thank you

Ron

Sales@KCLinear.com

### Assembly Instructions: http://KCLinear.com/G25

The G25 Shield IP is owned by Bright Light Investments LLC, 520 W 103<sup>rd</sup> St. Kansas City, MO 64114 all rights reserved.

# Selecting the pinout

There are two ways to set up GRBL. The v0.8 and v0.9 "Traditional" layout and then there is the v0.9 "PWM Enabled" layout. https://github.com/grbl/grbl/wiki/Connecting-Grbl

#### v0.8 & v0.9 Traditional layout

#### v0.9 PWM Enabled Layout



\* - Indicates input pins. Held high with internal pull-up resistors.

\* - Indicates input pins. Held high with internal pull-up resistors.

GRBL Traditional Layout			GRBL PWM Layout			Common CNC LPT Pinout	
Description	Arduino	db25	Description	Arduino	db25	Pin	Description
Reset/Abort	A0	10	Reset/Abort	A0	10	1	Output
Feed Hold	A1		Feed Hold	A1		2	X Direction
Cycle Start	A2		Cycle Start	A2		3	X Step
Coolant Enable	A3		Coolant Enable	A3		4	Y Direction
Probe	A5	15	Probe	A4	15	5	Y Step
Step X	D2	2	Step X	D2	2	6	Z Direction
Step Y	D3	4	Step Y	D3	4	7	Z Step
Step Z	D4	6	Step Z	D4	6	8	A Direction **
Direction X	D5	3	Direction X	D5	3	9	A Step **
Direction Y	D6	5	Direction Y	D6	5	10	Reset / Abort / E-Stop
Direction Z	D7	7	Direction Z	D7	7	11	X limit
Stepper Enable	D8		Stepper Enable	D8		12	Y limit
Limit X	D9	11	Limit X	D9	11	13	Z limit
Limit Y	D10	12	Limit Y	D10	12	14	A limit **
Limit Z	D11	13	Limit Z	D12*	13	15	Probe
Spindle Enable	D12	17	Spindle PWM	D11*	17	16	Enable **
Spindle Direction	D13	1	Spindle Direction	D13	1	17	Output

\*Pins are swapped to use internal PWM

\*\* Pinned out on PCB, but not mapped.

18 - 25 Ground

# Cut the headers

Break or cut the 1x40 male header into the following smaller headers.

- 1 1x6 (A0 to A5 header)
- 1-1x6 to 1x8 depending on board (Vin, GND,5v, 3.3v ect)
- 1 1x8 (D0 to D7)
- 1-1x8 (D8 to D13, gnd, aref)



The easiest way to solder the headers is to insert them into your Arduino board.



Place the CNC PCB on top. Please pay close attention to the orientation.



Solder the DB25 female connector.



This kit comes with a female db25 connector as most cnc machines will come with a male to male db25 cable. However, if you need to use a make connector, you can. Just be sure to solder it to the top side of the board to keep the pin number correct. If you solder a male connector to the bottom all of the pins will

If you need a male db25 connector, you will need to solder it to the opposite (top) side of the board.

# **PWM Layout**

If you are using GRBL v0.9 PWM Enabled configuration, then you need to do a few more steps.

Cut the U shaped traces near the 2x6 pads.

Solder two 1x3 male headers



"Traditional Layout"

"PWM Enabled Layout"



- D11 Z Axis Limit
- D12 Spindle Enable



- D12 Z Axis Limit
- D11 Spindle Enable

### **More Modifications**

All the db 25 pins (used or unused) have been pinned out. The circled are is the db25, pins as 0.1 headers (Pin 1 is on the right)



GRBL does not support an 'A' axis, but if your cnc mirrors the 'Y' and 'A' axis, you can do that with two jumpers.

Connect pin 4 (Y Dir) to pin 8 (A Dir). And connect pin 5 (Y Step) to pin 9 (A Step).

Now, Y Dir will be on db25 pins 4 and 8. Y Step will be on db25 pins 5 and 9

The "Prototyping Area" can be used for whatever you want. Status LEDs, Mosfet for controlling the spindle or pump.

